
Texas Department of Insurance

Windstorm Inspections Program

TDI Post-Hurricane Harvey



TDI Designated Catastrophe Areas

The 14 Texas Coastal Counties include:

Aransas Jefferson Nueces


Brazoria Kenedy Refugio

Calhoun Kleberg San Patricio

Cameron Matagorda Willacy

Chambers Galveston

Areas of Harris County east of State Highway 146 – Pasadena, Morgan's Point, Shoreacres, Seabrook and La Porte.



TDI Common Items Requiring Certification

Exterior wall coverings,
Roof coverings,
Roof vents & turbines
Skylights
Windows & entry
doors,

Garage doors,
Shutters,
Mechanical equipment,
Air conditioner units,
and
Solar panels.

TDI Know who is climbing your roof



TEXAS DEPARTMENT OF INSURANCE

Property & Casualty Program - Windstorm Inspections/ MC 103-1E 333 Guadalupe • P. O. Box 149104, Austin, Texas 78714-9104 (512) 322-2203 or Fax • (512) 322-2273

Certificate of Compliance WPI-8

Date of Construction:

Application ID:
Zone Type: RESIDENTIAL Building Type: HOUSE

Certification Type: Certification Detail: Certification Date: Engineer/Non-Engineer:
ROOF ENTIRE RE-ROOF NON-ENGINEERED

Location of Property to be Insured:
Street Lot Block Tract or Addition

street Lot

ity County State

INSIDE CITY LIMITS

THE INFORMATION CONTAINED IN THIS ELECTRONIC FORM HAS BEEN PROVIDED TO INDICATE EVIDENCE OF CERTIFICATION BY THE TEXAS DEPARTMENT OF INSURANCE. THIS INFORMATION CONFIRMS THAT THE CONSTRUCTION LISTED HAS BEEN EITHER ERECTED, ALTERED, AND/OR REPAIRED IN ACCORDANCE WITH THE BUILDING CONSTRUCTION REQUIREMENTS FOR WINDSTORM COVERAGE AS OUTLINED IN SECTION 64, ARTICLE 21.49 OF THE EXAS INSURANCE CODE.

TDI will:

WPI-8

- Process the WPI-1 for you and give you an App ID number
- Give you a WPI-7 at the job site and let you know of any issues
- Print a WPI-8 for you

Inspection of decking

- Existing decking must be a nailable surface or replaced
- New decking type, thickness and fastening patterns



Inspection of valley linings



- ASTM D
 Standard of self-adhered or rolled material
- Thickness and width of metal valley linings
- Applied under underlayment

Inspection of underlayment

- ASTM DStandard
- Fastener type, length, corrosion resistance, depth, location and spacing
- Lapping of underlayment



Inspection of roof covering



- ASTM DStandard
- Fastener type, length, corrosion resistance, depth, location and spacing
- Shingle application


Inspection of Roof components

- Identification of products
- Fastener diameter, length, type, and location
- Substrate being attached to



TDI Exterior Windows

Inspection of windows



- Identification of products
- Fastener type, length, corrosion resistance, depth, location and spacing
- Wall framing
- Windborne debris protection

TDI Shutters

Inspection of Windborne Debris Protection

- Identification of products
- Fastener type, length, corrosion resistance, depth, location and spacing
- Wall framing



TDI Exterior Entry Doors

Inspection of doors



- Identification of products
- Fastener type, length, corrosion resistance, depth, location and spacing
- Wall framing
- Windborne debris protection

TDI Garage Doors

Inspection of garage doors



- Identification of products
- Fastener type, length, corrosion resistance, depth, location and spacing
- Door construction
- Windborne debris protection

TDI Exterior Wall Coverings

Inspection of wall coverings

- Identification of products
- Water Vapor protection
- Material type, thickness and application
- Fastener diameter, length, type, and location



TDI Windstorm Inspections Program

Insert Video

TDI Let us know how we can help you!

Contact TDI Field Offices at:

800-248-6032

- Choose Option 4 for the field
- Choose Option
 - 1. Beaumont
 - 2. La Marque
 - 3. Angleton
 - 4. Corpus Christi

TDI Let us know how we can help you!

Contact Education / Oversight Inspector at:

800-248-6032

Choose Option 6

For Mike Babin (Angleton)

- Extension 39004

For Doug Klopfenstein (Corpus Christi)

- Extension 39203

TDI Thank you for your attention!

